




Spare Parts List




M1 Trend


2007-06-27



Pos. No.	Order no.	Notes	Pos. No.	Order no.	Notes
1	6120-01				
2	6142-01				
3	6143-01				
4	4470-01				
5	6340-05				
6	9990-52				
7	6140-01				
8	9962-04	M8x20			
9	9930-32	D8/17			
10	9969-31	M8			
11	9962-03	M8x16			
12	9990-07				
13	9990-43				
14	9930-03	D6/17			
15	6910-81				
16	6171-01				
17	6171-09				
18	9961-11	M6x12			
19	9930-02	D6/12			
20	9969-16	M6			
21	6174-01				
22	6174-02				
23	9961-14	M6x25			
24	9969-15	M6			
25	9985-24	560 mm			



Pos. No.	Order no.	Notes	Pos. No.	Order no.	Notes
1	6111-00				
2	9990-53				
3	4416-01				
4	9934-34				
5	6110-01				
6	6110-03				
7	9962-05	M8x25			
8	2810-18	D8/25			
9	9930-32	D8/17			
10	9969-32	M8			
11	9962-04	M8x20			
12	6141-02				
13	6141-01				
14	4412-20	Big			
15	4412-21	Small			
16	4412-08	Small, Left			
17	4412-09	Small, Right			
18	4412-05	Big, Left			
19	4412-06	Big, Right			
20	4611-01				
21	9934-31				
22	9990-43				
23	6112-01				
24	4012-11				
25	9937-30	U44			
26	9933-25	Ø2x10			



Pos. No.	Order no.	Notes	Pos. No.	Order no.	Notes
1	6150-02	540/750 rpm	42	4652-03	
2	4160-01	Right	43	4652-08	
3	4160-02	Left	44	4652-10	17/24 teeth
4	4056-10		45	4652-09	
5	4056-03		46	9950-03	6206-2RS
6	4058-05	Right	47	4652-01	
7	4058-06	Left	48	3260-09	
8	4161-02	Left	49	9990-90	
9	4161-01	Right	50	3263-00	
10	4158-05		51	3260-07	
11	9913-20		52	9965-02	M12x65
12	4560-01	Ø20xØ30x5	53	9934-03	
13	9933-02	Ø8x40	54	9969-60	M12
14	9933-11	Ø5x40	55	4653-10	
15	6151-01	Left	56	9934-02	
16	6151-02	Right	57	4653-02	
17	6150-12	2 ML / 2 MR	58	9990-99	14x20x10
18	9936-37	35x62x12	59	9936-29	14x22x4
19	9950-02	6305-2RS	60	9934-01	
20	4155-04	Right thread	61	9930-51	PA.
21	4062-05	Left thread	62	9934-31	
22	4454-05		63	4653-20	
23	9933-12	Ø8x45	64	9930-07	D6/17
24	9933-17	Ø5x45	65	9961-04	M6x16
25	3265-02	15 teeth	66	9936-28	
26	9937-40	I60	67	9937-13	U14
27	3262-05				
28	3260-04				
29	9913-43	M10x25			
30	3260-05				
31	6157-02				
32	6156-02				
33	9931-56	8x7x25			
35	9969-31	M8			
36	9962-03	M8x16			
37	6150-04				
38	9962-15	M8x30			
39	9930-32	D8/17			
40	9969-32	M8			
41	4660-00				



Spare parts list *M1 Trend* from machine no. 101

**Reservedelsliste
Ersatzteilliste
Reservdelslista
Lista de piezas de recambio
Liste de pièce de rechange
Onderdelenslijst
Varaosaluettelo**

BOGBALLE A/S

Bogballe · DK-7171 Uldum

Tel.: +45 7589 3266

Fax: +45 7589 3766

E-mail: bogballe@bogballe.com

www.bogballe.com